

GOVERNMENT OF ANDHRA PRADESH
ABSTRACT

General Administration Department – Secretariat Buildings – Urgent repairs to Room No.303, 3rd Floor, South H-Block in the premises of A.P. Secretariat – Submission of estimate – Administrative Sanction – Orders – Issued.

GENERAL ADMINISTRATION (SB) DEPARTMENT

G.O.RT.No. 616

Dated: 28.02.2015

Read:-

From the Executive Engineer (R&B) Buildings Division, Hyderabad.
Lr.No.EE(R&B) /Bldgs Division / AP SEC/2014-15, Dated: 18.2.2015
&&&

ORDER:

In the circumstances reported by the Executive Engineer (R&B) Buildings Division Hyderabad in the reference read above and after examination of the matter, Government hereby accord administrative sanction for an amount of Rs.1,55,000-00 (Rupees One Lakh Fifty Five Thousand only) towards Urgent repairs to Room No.303, 3rd Floor, South H-Block in the premises of A.P Secretariat, Hyderabad on the responsibility of Executive Engineer (R&B) Buildings, Hyderabad and also subject to production of the work done certificate at the time of issue of L.O.C.

2. The expenditure shall be debited to the head of account "2059 Public works – 01 Office buildings - MH 053 Maintenance and repairs – SH(10) Buildings of General Administration Department – 270 Minor works – 272 Maintenance"

3. This order does not require the concurrence of Finance Department in terms of Circular Memo.No.7088/049/A/BG/2000-1, dated 25.10.2002.

(BY ORDER AND IN THE NAME OF THE GOVERNOR OF ANDHRA PRADESH)

MUKESH KUMAR MEENA
SECRETARY TO GOVERNMENT
(POLL.)

To
The Executive Engineer (R&B) Buildings Division, Hyderabad.

Copy to:

The Dy.E.E.(R&B) Buildings, Sectt. Sub-Division.

//Forwarded By Order//

SECTION OFFICER